

























AUSWAHLHILFE SENKERODIEREN

Elektrodenmaterialien			Spannsystem				Allgemeines Zubehör		
			ITS-50	ITS-100	System ITS	System 1		System 1	
Messing	Kupfer (2.0060)	Graphit (Q70, Q60, Q40)	Elektrodenhalter		Spannsystem - Zubehör	Elektrodenhalter		Spannsystem - Zubehör	
	V 91371 V 91570 V 91571	V 9237X V 9258X V 9257X	HER 1112	HER 1412 HER 1472	HER 1672	HER 1212 HER 1272	HER 1118 HER 2320		
	V 91381 V 91811	V 9238X	HER 1442	HER 1642	HER 1805	HER 1242			
V 93240 V 93250 V 93255	V 91411 V 93210 V 93220 V 93225 V 93110 V 93120 V 93140 (WCu)	V 93160	HER 1130	HER 1130/SET	HER 1810	HER 1230 HER 1230/SET	HER 1910 V 32910 HWZ 9719 HER 1839 HWZ 9000		
	V 91550 V 91552 V 91554 V 91556	V 9255X V 9256X	V 95500	+	HER 1112	V 95500	+	HER 1212	V 95500 HER 2320
	V 91311	V 9231X V 9232X	V 95500	+	HER 1412	HER 1822 HER 1824 HER 1890	HER 1222		
	V 91311		HER 1122	HER 1422	HER 1622	HER 1222			
	V 91311		HER 1180	+	HER 1112			HER 1860	
	V 91811	V 9222X	HER 1180	+	HER 1412				
			HER 1680		HER 1822				
			HER 1185			HER 1815			
			HER 1144		HER 1824				



	Spannsystem				Allgemeines Zubehör	
	 ITS-50	 ITS-100	System ITS	 System 1		System 1
Mess- und Kontrollelemente	 HER 2110		 HER 2410		 HER 2160	
	 HER 2112		 HER 2412			 HER 2162
	 HER 2230/30		 HER 2530			
Elektrodenbearbeitung	 HER 1118					
	 HER 3010	 HER 3012	 HER 3530	 HER 3534		
	 HER 3030	 HER 3032	 HER 3532	 HER 3535		
	 HER 3040					
System - Adapter	 HER 3080		 HER 3580			
	 HER 3082					

